



Bench and pedestal grinders

- ✓ Eye protection
- ✓ Hearing protection
- ✓ No loose hair or clothing
- ✓ Bottom guard 1/8"
- ✓ Top guard 1/4"



Supporting the work

- ✓ Secure with jack.
- ✓ Support with blocks or stand.
- ✓ Crib stack blocks.
- ✓ Block wheels.
- ✓ Remove keys or energy.
- ✓ Check weight limits.



Arc welding

- ✓ Face protection
- ✓ Eye protection
- ✓ Long sleeve shirt
- ✓ Gloves
- ✓ No flammable debris
- ✓ Ventilation
- ✓ Flash screen protector
- ✓ Galvanized metal or stainless steel respirator



Hand grinders

- ✓ Guard securely in place
- ✓ No flammable material nearby
- ✓ Gloves
- ✓ Face protection
- ✓ Eye protection
- ✓ Hearing protection



Energy control

- ☒ Remove keys.
- ☒ Unplug power.
- ☒ Attach lockout device.
- ☒ Maintain control of energy.
- ☒ Tag equipment out of service.



Compressed air

- ☒ Safety nozzle
- ☒ Avoid skin/body contact.
- ☒ Eye protection



Housekeeping

- ☑ Clear walkways.
- ☑ Clean up spills.
- ☑ Perform equipment maintenance checks
- ☑ Pick up tools
- ☑ Properly dispose of oily rags
- ☑ Remove dust and shavings.
- ☑ Service fire extinguishers.
- ☑ Store flammable items safely.
- ☑ Service and clean eye wash station.
- ☑ Clear paths to electrical panels and exits